

**Viareggio October 14, 2016**

The following table shows the latest official releases of the firmware for the power supply boards installed in LHC experiments.

**Latest updates shown in Yellow Highlight:**

Module	Release	Date	Note
<b>A1396A</b>	<b>1.11</b>	<b>31.12.12</b>	
A3025, A3050, A3100	2.04	05.05.08	
A3025D	1.03	05.05.08	
A3050D	1.03	05.05.08	
A3025A	1.00	22.05.09	
A3486 A3486S	2.04	07.05.08	
A3501	3.01	29.05.09	
A3512	3.03	06.11.08	
A3512A	1.01	06.11.08	
A3540	3.01	29.05.09	
A3540A	1.01	29.05.09	
A3602	1.01	07.05.08	
A3009	2.05	05.05.08	
A3016	2.05	05.05.08	
<b>A3801</b>	<b>3.01</b>	<b>25.03.11</b>	
A3802	1.01	06.05.08	
<b>A4601H</b>	<b>1.05</b>	<b>14.04.11</b>	
A4602	1.03	07.05.08	
<b>A4603</b>	<b>1.04</b>	<b>05.11.09</b>	
A876	3.02	01.02.10	
A877MN	3.02	01.12.02	
A877SN	4.01	01.02.02	
A1511	4.00	31.01.14	(*)
A1512	4.00	20.05.13	(*)
<b>A1513A</b>	<b>4.00</b>	<b>04.10.13</b>	<b>(*)</b>
A1516A	4.00	20.05.13	(*)
A1519	4.00	07.02.13	(*)
<b>A1520 PE</b>	<b>4.01</b>	<b>21.12.15</b>	
A1526	4.00	07.02.13	(*)
A1534	3.01	13.05.09	
<b>A1535</b>	<b>4.01</b>	<b>03.12.14</b>	<b>(*)</b>
<b>A1550</b>	<b>4.01</b>	<b>03.12.14</b>	<b>(*)</b>
A1676A	3.02	01.12.09	
A1733BP	4.00	28.07.08	
A1735	5.00	02.05.13	(*)
A1821	6.00	19.02.14	(*)
A1833BP	4.00	28.07.08	
A2818	0.8	10.04.04	CONET1
	1.0	01.01.11	CONET2
SY1527 SY2527	2.01.02 / 3.02.00	01.09.06 / Feb 2012	Depending on hardware
<b>V1718 VX1718</b>	<b>2.14</b>	<b>07.04.14</b>	
V2718 VX2718 VN2738 U2 (Mezzanine Card A2719)	0.5	19.01.05	CONET1
	1.5	30.08.13	CONET2
<b>V2718 VX2718 VN2738 U6 (MotherBoard)</b>	<b>2.14</b>	<b>07.04.14</b>	
SY4527/LC (A4534 LCD Display)	1.3.0	01.11.12	
<b>SY5527/LC (A5534 LCD Display)</b>	<b>1.2.1</b>	<b>01.06.15</b>	
SY4527/LC SY5527/LC (HV Control firmware)	1.3.1	01.06.15	
<b>SY4527/LC SY5527/LC (HiVoCS)</b>	<b>1.4.0</b>	<b>01.08.16</b>	

(\*) Added compatibility with ST10F276 Microcontroller installed on A1000 CPU Board. Officially released in February 2014.